



**Compressor
Systems, Inc.**

547-548

January 24, 2011

Kansas Dept. of Health & Environment
Division of Environment
Bureau of Air
Air Compliance Section
1000 SW Jackson, Suite 310
Topeka, Kansas 66612-1366

REC'D
JAN 28 2011
APCO

CERTIFIED MAIL # 7008 1830 0004 2748 1704
RETURN RECEIPT REQUESTED

Subject: Title 40 CFR Part 63, NESHAP Subpart ZZZZ Initial Notification

Attached are initial notification forms that are submitted in accordance with NESHAP Subpart ZZZZ requirements in 40 CFR §63.6645(a)(2) and §63.9(b)(2).

If you have any questions or need additional information, please contact me.

Thank you,

David O'Leary
Environmental Manager
Compressor Systems, Inc.
432-495-3106
david.oleary@warren-equipment.com

Enclosures: NESHAP ZZZZ Initial Notifications (4)

cc: United States Environmental Protection Agency Region 7
Director, Air, RCRA & Toxics Division
901 North 5th Street
Kansas City, Kansas 66101

vll

547

**Initial Notification Form - 40 CFR Part 63, Subpart ZZZZ
NESHAP for Reciprocating Internal Combustion Engines (RICE)**

CSI Unit Number: 411089

- ☒ Yes, the spark ignited RICE indicated on this form is subject to 40 CFR Part 63 Subpart ZZZZ National Emission Standards for Hazardous Air Pollutants for Stationary Reciprocating Internal Combustion Engines
- Source's current operating facility is a (please choose one)¹: ☐ Major source ☒ Area source

¹**Note to Administrator:** This information is provided to the best of CSI's knowledge. CSI is a RICE compressor leasing company that owns but does not control the affected RICE or stationary source of which the affected RICE is a part.

Compliance Date (see Instructions if the following source categories do not apply):

- ☒ October 19, 2013 – existing spark-ignited [SI] RICE ≤ 500 HP located at a major source, or existing SI RICE > 500 HP located at an area source.
- ☐ Upon Initial Startup - new/reconstructed source

Owner Information

Company name & NAICS Code(s): Compressor Systems, Inc. (CSI), NAICS 532412
Owner's contact name/title: David O'Leary – Environmental Manager
Owner company address: P.O. Box 60760, Midland, TX 79711
Owner telephone number: (432) 563-1170

Operator Information² (If the facility Operator is different from the Owner)

Operator company name: Cherokee Basin Pipeline, LLC
Operator's contact name: Bill Barks
Operator company address: 211 West Myrtle, Independence, KS 67301-7942
Operator telephone number: 620-332-2405

²**Note to Administrator:** It is stated in §63.6645 that initial notifications are to be submitted "if you own or operate" RICE identified in this section. Although this notification requirement clearly applies to operators, CSI is a RICE compressor leasing company that owns but does not control the affected RICE or stationary source of which the affected RICE is a part. Accordingly, the applicability of initial notification requirements to CSI is unclear. CSI elects to submit this initial notification as a precautionary measure.

Current Operating Facility Information

Facility name: Pod #1 lease
Current facility (physical location) address: Wilson County, KS

Source Description – Provide in the following test box a "brief description of the nature, size, design, and method of operation of the source and an identification of the types of emission points within the affected source subject to the relevant standard and types of hazardous air pollutants emitted". (See Instructions)

Indicate engine type (4SLB, 4SRB, 2SLB), horsepower, manufacturer, model, serial number, subcategory (existing, new, or reconstructed), and reconstruction date (if applicable)⇒

4SLB, 637 HP @1800 rpm, Caterpillar G3412TALELCR, Serial # 6ZM02667, Existing NESHAP Subpart ZZZZ affected source

Note: HAPS that may be emitted by gas-fired spark ignited RICE include Formaldehyde, Acrolein, Ethylbenzene, Toluene, Xylenes, Hexane and Benzene.

I hereby certify that the information presented herein is correct to the best of my knowledge.


(Signature)

David O'Leary, CSI Environmental Manager
(Name/title)

1-18-2011
(Date)

(432) 495-3106
(Telephone No.)

547

**Initial Notification Form - 40 CFR Part 63, Subpart ZZZZ
NESHAP for Reciprocating Internal Combustion Engines (RICE)**

CSI Unit Number: 411272

☒ Yes, the spark ignited RICE indicated on this form is subject to 40 CFR Part 63 Subpart ZZZZ National Emission Standards for Hazardous Air Pollutants for Stationary Reciprocating Internal Combustion Engines

Source's current operating facility is a (please choose one)¹: ☐ Major source ☒ Area source

¹**Note to Administrator:** This information is provided to the best of CSI's knowledge. CSI is a RICE compressor leasing company that owns but does not control the affected RICE or stationary source of which the affected RICE is a part.

Compliance Date (see Instructions if the following source categories do not apply):

- ☒ October 19, 2013 – existing spark-ignited [SI] RICE ≤ 500 HP located at a major source, or existing SI RICE > 500 HP located at an area source.
☐ Upon Initial Startup - new/reconstructed source

Owner Information

Company name & NAICS Code(s): Compressor Systems, Inc. (CSI), NAICS 532412
Owner's contact name/title: David O'Leary – Environmental Manager
Owner company address: P.O. Box 60760, Midland, TX 79711
Owner telephone number: (432) 563-1170

Operator Information² (If the facility Operator is different from the Owner)

Operator company name: Cherokee Basin Pipeline, LLC
Operator's contact name: Bill Barks
Operator company address: 211 West Myrtle, Independence, KS 67301-7942
Operator telephone number: 620-332-2405

²**Note to Administrator:** It is stated in §63.6645 that initial notifications are to be submitted "if you own or operate" RICE identified in this section. Although this notification requirement clearly applies to operators, CSI is a RICE compressor leasing company that owns but does not control the affected RICE or stationary source of which the affected RICE is a part. Accordingly, the applicability of initial notification requirements to CSI is unclear. CSI elects to submit this initial notification as a precautionary measure.

Current Operating Facility Information

Facility name: Pod #1 lease
Current facility (physical location) address: Wilson County, KS


Source Description – Provide in the following test box a "brief description of the nature, size, design, and method of operation of the source and an identification of the types of emission points within the affected source subject to the relevant standard and types of hazardous air pollutants emitted". (See Instructions)

Indicate engine type (4SLB, 4SRB, 2SLB), horsepower, manufacturer, model, serial number, subcategory (existing, new, or reconstructed), and reconstruction date (if applicable)⇒

4SLB, 637 HP @1800 rpm, Caterpillar G3412TALELCR, Serial # 6ZM02670, Existing NESHAP Subpart ZZZZ affected source

Note: HAPS that may be emitted by gas-fired spark ignited RICE include Formaldehyde, Acrolein, Ethylbenzene, Toluene, Xylenes, Hexane and Benzene.

I hereby certify that the information presented herein is correct to the best of my knowledge.


(Signature)

David O'Leary, CSI Environmental Manager
(Name/title)

1-11-2011
(Date)

(432) 495-3106
(Telephone No.)

548

**Initial Notification Form - 40 CFR Part 63, Subpart ZZZZ
NESHAP for Reciprocating Internal Combustion Engines (RICE)**

CSI Unit Number: 410670

☒ Yes, the spark ignited RICE indicated on this form is subject to 40 CFR Part 63 Subpart ZZZZ National Emission Standards for Hazardous Air Pollutants for Stationary Reciprocating Internal Combustion Engines

Source's current operating facility is a (please choose one)¹: ☐ Major source ☒ Area source

¹**Note to Administrator:** This information is provided to the best of CSI's knowledge. CSI is a RICE compressor leasing company that owns but does not control the affected RICE or stationary source of which the affected RICE is a part.

Compliance Date (see Instructions if the following source categories do not apply):

- ☒ October 19, 2013 – existing spark-ignited [SI] RICE ≤ 500 HP located at a major source, or existing SI RICE > 500 HP located at an area source.
☐ Upon Initial Startup - new/reconstructed source

Owner Information

Company name & NAICS Code(s): Compressor Systems, Inc. (CSI), NAICS 532412
Owner's contact name/title: David O'Leary – Environmental Manager
Owner company address: P.O. Box 60760, Midland, TX 79711
Owner telephone number: (432) 563-1170

Operator Information² (If the facility Operator is different from the Owner)

Operator company name: Cherryvale Pipeline, LLC
Operator's contact name: Vic Dyal
Operator company address: 1900 Shawnee Mission Parkway, Mission Woods, KS 66205
Operator telephone number: 913-748-3955

²**Note to Administrator:** It is stated in §63.6645 that initial notifications are to be submitted "if you own or operate" RICE identified in this section. Although this notification requirement clearly applies to operators, CSI is a RICE compressor leasing company that owns but does not control the affected RICE or stationary source of which the affected RICE is a part. Accordingly, the applicability of initial notification requirements to CSI is unclear. CSI elects to submit this initial notification as a precautionary measure.

Current Operating Facility Information

Facility name: Boorigie lease
Current facility (physical location) address: Montgomery County, KS

Source Description – Provide in the following test box a "brief description of the nature, size, design, and method of operation of the source and an identification of the types of emission points within the affected source subject to the relevant standard and types of hazardous air pollutants emitted". (See Instructions)

Indicate engine type (4SLB, 4SRB, 2SLB), horsepower, manufacturer, model, serial number, subcategory (existing, new, or reconstructed), and reconstruction date (if applicable)⇒

4SLB, 1005 HP @1400 rpm, Caterpillar G3512TALEAFR, Serial # 7NJ00786, Existing NESHAP Subpart ZZZZ affected source

Note: HAPS that may be emitted by gas-fired spark ignited RICE include Formaldehyde, Acrolein, Ethylbenzene, Toluene, Xylenes, Hexane and Benzene.

I hereby certify that the information presented herein is correct to the best of my knowledge.


(Signature)

David O'Leary, CSI Environmental Manager
(Name/title)

1-18-2011
(Date)

(432) 495-3106
(Telephone No.)

548

**Initial Notification Form - 40 CFR Part 63, Subpart ZZZZ
NESHAP for Reciprocating Internal Combustion Engines (RICE)**

CSI Unit Number: 410932

☒ Yes, the spark ignited RICE indicated on this form is subject to 40 CFR Part 63 Subpart ZZZZ National Emission Standards for Hazardous Air Pollutants for Stationary Reciprocating Internal Combustion Engines

Source's current operating facility is a (please choose one)¹: ☐ Major source ☒ Area source

¹**Note to Administrator:** This information is provided to the best of CSI's knowledge. CSI is a RICE compressor leasing company that owns but does not control the affected RICE or stationary source of which the affected RICE is a part.

Compliance Date (see Instructions if the following source categories do not apply):

- ☒ October 19, 2013 – existing spark-ignited [SI] RICE \leq 500 HP located at a major source, or existing SI RICE > 500 HP located at an area source.
☐ Upon Initial Startup - new/reconstructed source

Owner Information

Company name & NAICS Code(s): Compressor Systems, Inc. (CSI), NAICS 532412
Owner's contact name/title: David O'Leary – Environmental Manager
Owner company address: P.O. Box 60760, Midland, TX 79711
Owner telephone number: (432) 563-1170

Operator Information² (If the facility Operator is different from the Owner)

Operator company name: Cherryvale Pipeline, LLC
Operator's contact name: Vic Dyal
Operator company address: 1900 Shawnee Mission Parkway, Mission Woods, KS 66205
Operator telephone number: 913-748-3955

²**Note to Administrator:** It is stated in §63.6645 that initial notifications are to be submitted "if you own or operate" RICE identified in this section. Although this notification requirement clearly applies to operators, CSI is a RICE compressor leasing company that owns but does not control the affected RICE or stationary source of which the affected RICE is a part. Accordingly, the applicability of initial notification requirements to CSI is unclear. CSI elects to submit this initial notification as a precautionary measure.

Current Operating Facility Information

Facility name: Boorigie lease
Current facility (physical location) address: Montgomery County, KS

Source Description – Provide in the following test box a "brief description of the nature, size, design, and method of operation of the source and an identification of the types of emission points within the affected source subject to the relevant standard and types of hazardous air pollutants emitted". (See Instructions)

Indicate engine type (4SLB, 4SRB, 2SLB), horsepower, manufacturer, model, serial number, subcategory (existing, new, or reconstructed), and reconstruction date (if applicable)⇒

4SLB, 1005 HP @1400 rpm, Caterpillar G3512TALEAFR, Serial # 7NJ01228, Existing NESHAP Subpart ZZZZ affected source

Note: HAPS that may be emitted by gas-fired spark ignited RICE include Formaldehyde, Acrolein, Ethylbenzene, Toluene, Xylenes, Hexane and Benzene.

I hereby certify that the information presented herein is correct to the best of my knowledge.


(Signature)

David O'Leary, CSI Environmental Manager
(Name/title)

1-18-2011
(Date)

(432) 495-3106
(Telephone No.)